

January 29, 2018

David P. Fortson, P.E., County Engineer Macon-Bibb County Engineering Department 780 Third Street Macon, GA 31201

Dear Mr. Fortson

The Natural Resources Conservation Service (NRCS) has completed the 5-year Operation and Maintenance (O&M) inspection on the following watershed facilities:

• Tobesofkee #1

As you are aware, the watershed project sponsor is responsible for maintaining dams installed through the Watershed Protection and Flood Prevention Program. Please refer to the enclosed copies of the Watershed Structure Inspection Report regarding the needed actions to make the dam safe and functional for the purposes of the project.

Please feel free to contact George Skovran, NRCS O&M State Dam Engineer at (706) 552-2537, for further guidance regarding the required maintenance work.

DIANE A. GUTHRIE, P.E.

Kin Them ACTIVIS

State Conservation Engineer

Attachment: O&M Inspection Reports (available on DamWatch at

https://dmt.sc.egov.usda.gov/nrcs-natl/main/main.html)

cc: Diane A. Guthrie, P.E., State Conservation Engineer, NRCS, Athens, GA
George Skovran, P.E., O&M State Dam Engineer, NRCS, Athens, GA
Randy Odom, P.E., Area Engineer, NRCS, Moultrie, GA
Floyd Hooker, Assistant State Conservationist for Field Operations, NRCS, Americus, GA
Tom Woosley, Program Manager, Georgia Dam Safety Program, Atlanta, GA

Marcus Griffin, District Conservationist, NRCS, Fort Valley, GA

U.S. DEPARTMENT OF AGRICULTUR Natural Resources Conservation Service		AM FII	ELD INSPECTION CHECKLIST	Rev 12/2017
State Georgia		9	Site Number 1 Inspection D	ate 12-04-2017
Watershed Tobesofkee		9	NID# GA00201	
County BIBB			Safe Dams Classification	
NRCS Class H			Purpose(s) of Dam Recreation, Industrial	H-14 - 155
Service Center Fort Valley NRCS Field	d Office		Weather Sunny, Warm	
Sponsor with Operation and Maintena	nce Responsibi	lity Bibb	County	
Latitude 32.8200	N L	ongitude		w
		Тур	of Inspection	Other
A hazard classification that is no longer accurate	or unknown w	ill need e	xplanation in Remarks section after checklist.	
"YES" responses need explanation added to "Res	marks" section.	(i.e.: Wh	at? Where? Extent?)	
"NO" responses indicate problems not observed	during inspect	ion.		
Non-applicable items should be noted by N/A.				
ITEM	Y	N N/A	REMARKS	
1. General Condition				
a. Alterations to Dam?				
b. Recent high water marks? (elevatio	n)	$\mathbf{V} \square$		
c. Fencing inadequate?		$\mathbf{Z} \Box$		
d. Development in flood pool?		7		
e. Easement Violations?		√ □		hite on how
2. Dam Crest: earthen vegetated	concrete	paved	gravel other (specify):	7
a. Is condition of surface material inadequate?				
b. Erosion/rutting evident?		$I \square$		
c. Trees/woody vegetation?		$\mathbf{Z} \square$		
d. Rodent holes?		\checkmark		
e. Settlement, obstructions or other concerns?		7		
3. Upstream Slope		200		
a. Is vegetative cover inadequate?		$\mathbf{Z} \square$		
b. Cracks, settlements or bulges?		$\mathbf{Z} \Box$		
c. Distinct Vegetation Change?		$oldsymbol{V}$		
d. Vehicle Ruts?		✓		
e. Animal Trails?		√	1.	
f. Trees?		\checkmark		
g. Rodent holes?		√		
h. Is riprap inadequate?		√	L. Carlotte and Ca	

4. Downstream Slope							
a. Is vegetative cover inadequate?			1				
b. Cracks, settlements, & bulges?		1	1		T		
c. Seepage or boils?			1	1			
d. Distinct Vegetation Change?]	V		1	I	location
e. Vehicle ruts?			1	1		ı	
f. Animal trails?]	V	1		I	
g. Trees?		1	V				
h. Rodent holes?			V				
5. PSW Intake Structure concrete metal							Water Surface Elevation
a. Spalling, cracking, & scaling?	V	П					Calcium carbonate leaching in various areas on spillway walls
b. Exposed reinforcement?		1	V		Γ	Ĩ	
c. Corrosion present?		I	V	1	Γ		
d. Manhole cover present?					V	7	
e. Leakage?	V						Both gates leak at bottom seals
f. Trash rack adequate?					V	7	
g. Inlet or trash rack obstructed?					V	7	
h. Ladder not intact?					V	7	
i. Pedestal not securely fastened?					V	7	
j. Stem bent?					V	7	
k. Stem guides not operational?]	V	7	
I. Stem handwheel missing?					V	7	
m. Do metal parts require painting?			V	1			Repainting to be completed in the next few years
n. Was gate determined not operational?			V				Date gate last operated: Left side opened during inspection
o. Has inlet been modified to alter water surface?			V	7			
p. Is there structural movement?			V				
q. Is access door missing?					V	$\overline{\Delta}$	
6. Abutment Contacts							
a. Erosion, cracks, or slips?		\prod	V		L		
b. Seepage?	TE	\prod	V				
c. Gutters not intact?			✓				
d. Trees encroaching?		\prod	✓	7			
7. Auxiliary Spillway							San and the san
a. Obstructions?					V	7	Trunion gate systems serve as both principle and auxiliary
b. Is vegetative cover inadequate?					V		spillway
c. Is Control Section disturbed?					V		
d. Roads, vehicle ruts, or animal trails?					V	1	
e. Low areas or ditches?					V	1	
f. Seepage?		1		7	Ī,	7	

8. PSW Conduit concrete metal					tailwater elevation/flow
a. Spalling, cracking, & scaling?			brack brack	√	
b. Exposed reinforcement?					
c. Joints displaced or offset?				V	
d. Joint material lost?				\checkmark	
e. Leakage?					
f. Conduit misaligned?				√	
g. Was pipe inspected internally?][\checkmark	
9. Stilling Basin Plunge Pool					
a. Spalling, cracking, & scaling?			$ lab{1}$	\checkmark	
b. Exposed reinforcement?					
c. Joints displaced or offset?			floor	√	
d. Joint material lost?			floor	$oldsymbol{}$	
e. Joints leak?			$ lab{I}$	√	
f. Dissipater deteriorating?][
g. Dissipater clean of debris?			floor		
h. Toe drains not visible?		√	1		
i. Toe drains flowing?		V			
j. Toe drain animal guards missing?		V			
k. Toe drains damaged or restricted?		V			
I. Earth erosion?		V			
m. Is riprap inadequate?		V	1		
10. Principal Spillway Release Channel					
a. Does scour hole appear unstable?	$\Pi \Box$	V	$ label{eq:linear_continuous}$		
b. Any boils observed?	$\Pi \square$	V	$ label{eq:linear_property} egin{array}{c} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$		
c. Is riprap inadequate?		V	7		
d. Any seepage observed?		V			
e. Is conduit outlet submerged?			\prod	1	
f. Is conduit outlet not properly supported?				√	
g. Is outlet channel obstructed?		V			
h. Is outlet channel degrading?		V	7		

11. Reservoir at 🗸 abovebelow norm	al pool				
a. Buildings in floodpool?	$\overline{\mathbf{V}}$		Ш		Boathouses
b. Slips or erosion on banks?		✓	Щ		
c. Debris?		✓			
d. Unsecured boats/docks?		✓			
e. Visible sediment deposits?		V			
12. Instrumentation				_	
a. Structure instrumented?][[
b. Monitoring performed?] [•		
13. Development					
a. New development upstream of dam?		IV			
b. New development downstream of dam?					None visible
c. EAP plan and mapping adequate?					EAP currently being prepared
REMARKS: Embankment is receiving regular ma	Interiorio	and			Throwest recently.

INCRECTION	DATE	12-04-2017
INIXPE III IN	11011	12 0 1 20 1 1

George Skovran Diane Guthrie State Cons Molly Dawson, Mark Hall, Brandon Quinn Steve Blackston Randy Odom, Alan Woodward David Fortson Donald Bracewell Charles Brooks ACTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requestioning to the property of the p	am Eng. NRCS Eng. NRCS Office NRCS Ing. N
Diane Guthrie State Cons Molly Dawson, Mark Hall, Brandon Quinn Athens State Steve Blackston Randy Odom, Alan Woodward David Fortson Donald Bracewell Charles Brooks Charles Brooks CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	NRCS Property of the County of the Dir. NRCS NRCS NRCS NRCS NRCS NRCS Macon-Bibb County Macon-Bibb County Macon-Bibb County Macon-Bibb County
Molly Dawson, Mark Hall, Brandon Quinn Steve Blackston Randy Odom, Alan Woodward David Fortson Donald Bracewell Charles Brooks County Enginee CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance required.	e Office NRCS gineer NRCS ing. NRCS gineer Macon-Bibb County te Dir. Macon-Bibb County r IV Macon-Bibb County
Steve Blackston Area 1 Eng Randy Odom, Alan Woodward Area 3 E David Fortson County Eng Donald Bracewell Tobesofke Charles Brooks Enginee CCTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	gineer NRCS ing. NRCS gineer Macon-Bibb County te Dir. Macon-Bibb County r IV Macon-Bibb County
Randy Odom, Alan Woodward David Fortson County Eng Donald Bracewell Charles Brooks Charles Brooks Enginee CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	ing. NRCS gineer Macon-Bibb County te Dir. Macon-Bibb County r IV Macon-Bibb County
David Fortson County Eng Donald Bracewell Tobesofke Charles Brooks Enginee CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	gineer Macon-Bibb County e Dir. Macon-Bibb County r IV Macon-Bibb County
Donald Bracewell Tobesofke Charles Brooks Enginee CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	e Dir. Macon-Bibb County r IV Macon-Bibb County
Charles Brooks Enginee CTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	r IV Macon-Bibb County
ACTIONS NEEDED: identify items by priority: Low (next 12 months); High (as soon as possible). Indicate date assistance requ	
Low (next 12 months); High (as soon as possible). Indicate date assistance requ	ested; technical or financial.
s noted on previous inspections, there is some calcium carbonate leaching on multiple location	ons of the spillway walls. These areas should be
D&M Non-Compliance Issues	
	Drain pipe problems.
1. Human Safety (such as missing access cover(s). 7. I	Drain pipe problems. Severe embankment erosion.
1. Human Safety (such as missing access cover(s). 7. I 2. Trash rack or parts of trash rack missing. 8. S	
1. Human Safety (such as missing access cover(s). 2. Trash rack or parts of trash rack missing. 3. Trash rack debris blockage.	Severe embankment erosion.
1. Human Safety (such as missing access cover(s). 2. Trash rack or parts of trash rack missing. 3. Trash rack debris blockage. 4. Principal spillway clogged. 5. Severe erosion of principal spillway outlet.	Severe embankment erosion. Flood pool storage alteration. . Severe tailwater issues. . Auxiliary spillway blockage (usually fence or tre
1. Human Safety (such as missing access cover(s). 2. Trash rack or parts of trash rack missing. 3. Trash rack debris blockage. 4. Principal spillway clogged. 5. Severe erosion of principal spillway outlet. 6. Auxiliary spillway without complete dense	Severe embankment erosion. Flood pool storage alteration. . Severe tailwater issues. . Auxiliary spillway blockage (usually fence or tre spillway).
2. Trash rack or parts of trash rack missing. 3. Trash rack debris blockage. 4. Principal spillway clogged. 5. Severe erosion of principal spillway outlet. 6. Auxiliary spillway without complete dense permanent vegetative cover in the control or exit	Severe embankment erosion. Flood pool storage alteration. . Severe tailwater issues. . Auxiliary spillway blockage (usually fence or tre

WATERSHED TO	besofkee	SITE NUMBER 1	INSPECTION DATE 13
	Inspection Acknowledged by: SPONSOR REPRESENTATIVE:	David P. Fartson, P.E. Printed Name	
	Title:	County Engineer Our P. Frates Signature/Date	- 49/18
	inspection Acknowledged by: SPONSOR REPRESENTATIVE:	Printed Name Dicerter Late Tobes	
	,	Signature/Date	
	Dam Inspected by:		
	ENGINEER (NRCS or OTHER):	George Skovran Printed Name	PROFESSIONAL ENGINEER SEAS (IF OTHER)
	Title: _	O&M State Dam Engineer Signature/Date	1/12/18

DISTRIBUTION:

Original - State Conservation Engineer (with all documentation)

Checklist Reviewed and Approved by:

STATE CONSERVATION ENGINEER:

Title:

Coples - Sponsor or Owner, Field Office

Diane A. Guthrie

Printed Name

State Conservation Engineer

Signature/Date

01/25/2018